



Owner: County Council of Talbot County

TPA: 1,100' AMSL

RWY	04/22	5,500' X 100'	ASPHALT	DSPL: 22 = 325'
RWY	15/33	4,003' X 100'	ASPHALT	DSPL:

Loc: 2 mi N of EASTON Unicom: 122.950 CTAF: 118.525

Lat: 38-48-15.420N Long: 76-04-07.190W Tower: 118.525 Ground: 119.075

Mgr: Mike Henry AWOS/ASOS: 124.475
 410-770-8055 mhenry@talbgov.org Phone: 410-822-2817

Attendance: 0800L-Dusk ATIS: 124.475

Right Traffic Pattern: 22 & 33; Tower Discretion VOR: N/A

Lights: Yes Pilot Controlled: Yes **118.525** NDB: N/A

Fuel: 100LL; A Other Svcs: INSTR; AVNCS; RNTL; CHTR; MAINT

FBO: Easton Aviation/Maryland Air Charter Easton Jet Service
 410-822-0400 410-820-8770

Rmks: Noise Abatement procedures in effect; Restaurant in terminal building operated 7AM-3PM daily; Car rentals available

Airport Name: Easton

Revised: 3-Feb-09

Revision Highlights:

Correction to airport sketch to indicate HIRL on runway 4/22. Correction of pilot controlled lighting frequency to 118.525

Cut at line and attach revision to directory page

Easton Airport / Newnam Field

ESN